



## Assembly instructions for adhesive lettering




As every surface is dirty / dusty, it should be cleaned with petrol before start gluing.




Place the lettering (label) on the desired position and align it with adhesive tape.




Align the adhesive tape (hinge) in the middle over the entire width.



Fold back half of the foil, put the carrier flat up to the hinge and pull it off. Cut the carrier foil with a clean cut, using sharp knife or scissor, along the hinge.



For gluing down 1 side of the foil, fold back the other half, avoiding any contact to the surface and keep it flat and straight. Starting at the hinge from the centre, press down the film and start scraping over the foil using the plastic blade.



Slowly pull off the transfer film at an angle of 180°.